


16 house Quench Dec, 5, 2003

Dean Still
Fermilab Tevatron Department
12/12/2003

Acknowledgments


The data, analysis and conclusions presented come from many people and departments in order to carefully and accurately describe the events of the 16 house quench on December 5, 2003. I would like to thank and acknowledge all those who contributed. The list of personnel is long but these are the main contributors: J. Annala, B. Hanna, T. Johnson, D. Wolff, B. Flora, N. Mohkov, S. Drozhdin, B. Hendricks and Mechanical support, CDF pot personnel.

Addition of A48 Collimator to Protect against A0 abort kicker prefires




CDF Pot 3 Position

Pots have been found in additional failure test to move at 1200mils/sec.





Reproduced after quench
On Dec 5, 2003



Similar incident on
~ 3/17/03

Pot 3 Pictures

Pots did NOT sustain any damage: Can conclude that they did not hit primary beam.



These are pictures before Dec 5, 2003

(Courtesy CDF Pot Personnel)

A48 Location

A48
Collimator

Pot 3


Pbar beam

In to beam

Proton Beam

X

Y



T44 loss of Quench



QPM Over Sample Buffer



Development of Quench:


A48U 16msec
D48L 13.5msec
F17L 13msec
E11U 12.5 msec

Before abort

(Courtesy D. Wolff
& EE Support)

A48 Bus Drawing

Protons



Displacement at D49 Target due to A48 Dipole Quench

location	betaX	phase advance	phase from col	radians	Displacement at collimator in mm
A47-4	61	20.3	10.933	68.69406	-0.026792767
A47-5	95	20.313	10.92	68.61238	-0.039417491
A48-3	215	20.324	10.909	68.54327	-0.066606399
A48-4	335	20.327	10.906	68.52442	-0.085562357
A48-5	480	20.33	10.903	68.50557	-0.105280213
D49 col	87	10.651	20.582	129.3205	-0.038580551

Using Dan Wolff's estimate that the current was coming out of A48U at a rate of 1/2 amp/msec.

A Dipole give 8 mrad of bend at 4350 amps, so we get 1.8 mrad of bend per amp.

The dipoles in the half cell are losing .9 mrad of kick per msec.

The displacement at the collimator is given by the sum of

$$Dx = q \sqrt{\beta_1 \beta_2} \sin(Y_2 - Y_1)$$

Where location 2 is the collimator, and location 1 is each of the dipoles in cell A48U


-0.362239778

Dx @ D49(mm) time

-0.36	1 msec
-0.72	2 msec
-1.09	3 msec
-1.45	4 msec
-1.81	5 msec
-2.17	6 msec
-2.54	7 msec
-2.90	8 msec
-3.26	9 msec

(Courtesy J. Annala Tevatron Dept.)

Damage to D49 Target



Damage to
D49 estimated
Took 20-30 turns
To create hole.

Once the hole
was open allowed
Beam to travel to
next limiting
horizontal aperture
which is E03

Simulation of losses on collimators






Figure 14: Particle hits at the collimators D49, E02, E03, F172 and at Roman Pot No.3 at dynamic simulations of quench of 5 main dipoles at A48 region. Time histogram of hits is shown on bottom-right of figure. Field degradation rate is $dB/B = 2.386 \times 10^{-5}$. Horizontal collimator F17(2) is retracted from working positions by 3 mm back, all others are retracted by 1 mm. The collimator D49 is assumed is melting with a rate of 0.04 mm per turn.

Damage to E03 1.5m Collimator




Protons


2 Stage Collimator System



N. Mokhov et.al, "Tevatron Run-II Beam Collimation System",
Proc. PAC 1999, or Fermilab-Conf -99/059.



6 inch Target w/ 5mm
Tungsten Wing



1.5 m collimator

Tevatron Collimator Layout

12 collimators total:

4 Targets

8 Secondary collimators

Arranged in 4 sets:

2 proton sets

2 pbar sets

Proton Set 1

D49 Tar, E03 & F172 2nd

Proton Set 2


D171 Tar, D173 & A0

Pbar Set 1


F49 Tar, F48 & D172

Pbar Set 2

F173 Tar, F171 & E02



Tevatron Ring Wide Loss Plot



Result of quench at C19.



Conning tower
correction
element damage
requiring C1
to be warmed to
room temp
for repair.

Conclusion:

- 1) The current Quench Protection System would NOT be able to catch this type of event because it processes data at 60Hz /16.67 msec.
- 2) It might have been possible to stop damage to collimators with different loss monitor protection system other than SVX. This needs discussion and possible loss monitor hardware system upgrade.
- 3) Even though 2 collimator devices were damaged, these devices defined the limiting aperture and are easy to change and provided protection to other components.